








Guidelines to Assembly Design

- Minimize parts
- Design assembly process in a layered fashion
- Consider ease of part handling
- Utilize optimum attachment methods
- Consider ease of alignment and insertion
- Avoid design features that require adjustments










Assembly business


Industry	% Workers in Assembly
Automobile	45.6%
Aircraft	25.6%
Telephone & Telegraph	58.9%
Farm Machinery	20.1%
Home appliances	32.1%
Two-wheel vehicles	26.3%

































































Good Design Principles: DFM Assembly

- Design parts to be self-locating and self-aligning
- Error-proof parts to make incorrect assembly impossible
- Minimize the number of parts.
- Minimize the number and variety tools for assembly
- Minimize the number of axes of insertion
- Ensure clear vision and access for all assembly operations
- Minimize the number and complexity of adjustments
- Eliminate the need to hold down, clamp or fixture parts
- Eliminate special assembly tools
 Alignmen



What assembly process to choose? Reasons to avoid assembly Reasons that justify assembly

Workholding

- Immobilization of a workpiece for machining or assembly
 - Jigs: locating and holding workpiece, guiding toolsFixtures: locating and holding
- Provide maximum accuracy and ease of mounting
- Datum

3-2-1 rule of locating 6 dof, (D_x, D_y, D_z) and (R_x, R_y, R_z) 3 support Points (1, 2 and 3) eliminate (R_x and R_y) and (-D_z); 2 points (4 and 5) eliminate (R_z) and (-D_z); and, 1 point (6) eliminates (-D_z). Push or clamp 3 directions, x,y,z.